

## Flat Springs


Steel, Accessories for Scaling Sets

### SPECIFICATION

Steel

### INFORMATION

The flat springs GN 374 are a perfect and virtually non-wearing connecting link between scale ring GN 264 (see page 597) and spindle or collar bushing GN 268 (see page 598). When adjusting the spindle, they ensure that the scale ring is safely driven without impairing the setting options of the ring when the shaft is at rest.



### GN 374

Description	s	b	l	
GN 374-0,3-10	0.3	10	21	1
GN 374-0,4-10	0.4	10	29	1
GN 374-0,6-10	0.6	10	45	2
GN 374-0,8-10	0.8	10	60	4